XMM-Newton CCF Release Note

XMM-CCF-REL-329

EPIC MOS Fixed Offset Tables

M.J.S. Smith

August 24, 2015

1 CCF Components

Name of CCF	VALDATE	EVALDATE	Blocks	XSCS
			Changed	Flag
EMOS1_DARKFRAME_0036.CCF	2015-08-12T14:50:00		OFFSET_CCD1	NO
			OFFSET_CCD2	
			OFFSET_CCD4	
			OFFSET_CCD5	
			OFFSET_CCD7	
EMOS2_DARKFRAME_0032.CCF	2015-08-12T14:50:00		OFFSET_CCD1	NO

2 Changes

Several columns in MOS1 peripheral CCDs, in particular CCD2, are producing a large number of noise events. These columns probably sustained damage in the 11 December 2012 impact event. The main objective of the latest MOS fixed offset tables is to suppress this noise through a suitable modification of the respective column offsets.

As additional objective, the new offset tables also address the canonical drift in background by lowering the column offsets for MOS1 SW and MOS2 LW modes by 1 ADU.

This set of CCFs reflect these modifications to the uploaded MOS fixed offset tables, which were implemented as of revolution 2871.

3 Scientific Impact and Estimated Quality

Note that the values in the OFFSET extensions of the DARKFRAME CCFs are not used to determine the E1 event energies; this is already done on board in the EDU. The main reason for reflecting the on board offset values in the DARKFRAME CCFs is correctly to determine the reconstructed event energies, for which knowledge of the contemporary on board offsets is required.

4 Expected Updates

As the effects of the CCD damage evolve, other MOS1 offset values may require modification.

Additionally, the background of all CCDs changes in time and will need to be compensated through periodic changes of the fixed offsets.

5 Test Procedures and Results

Correct functionality tested with cifbuild and emproc (SAS version 14.0.0). Reducing data with mismatched uploaded fixed offsets and DARKFRAME CCF issue may result in SAS warnings ** emevents: (spGatti11), reconstructed energy larger than 4095 [...]. As expected, use of the CCFs in this release result in correct reconstructed energies and no such warnings are issued.